



REVISIONS

ZONE	REV	DESCRIPTION	DATE	APPROVED
------	-----	-------------	------	----------



Actual


Alloy 6063-T5
 Metal: .062" typ.
 All corners .015" R
 Est. Wt. .199 #/ft.
 PPI 5.41 in.
 Industry Standard tolerances

Brunner Enterprises™ Inc

455 Center Road, West Seneca, NY 14224
 (877) 299-2622 toll-free (716) 712-0183 fax
 www.brunnerent.com

	SIZE	FSCM NO.	DWG NO. D1104	REV
	SCALE 4:1		SHEET	


REVISIONS				
ZONE	REV	DESCRIPTION	DATE	APPROVED



Actual

Alloy 6063-T5 Metal: .075" typ. All corners .015" R Est. Wt. .130 #/ft. PPI 3.20 in. Industry Standard tolerances	Brunner Enterprises™ Inc			
	455 Center Road, West Seneca, NY 14224 (877) 299-2622 toll-free (716) 712-0183 fax www.brunnerent.com			
	SIZE	FSCM NO.	DWG NO.	REV
			D1106	
	SCALE 4:1		SHEET	

REVISIONS				
ZONE	REV	DESCRIPTION	DATE	APPROVED



Actual

Alloy 6063-T5 Metal: .062" typ. All corners .015" R Est. Wt. .165 #/ft. PPI 4.45 in. Industry Standard tolerances	Brunner Enterprises™ Inc			
	455 Center Road, West Seneca, NY 14224 (877) 299-2622 toll-free (716) 712-0183 fax www.brunnerent.com			
	SIZE	FSCM NO.	DWG NO.	REV
			D2052	
	SCALE 2:1		SHEET	